



Fracture surface of an Al-Li alloy at different Working Distance (WD)



For further finding the reason of intergranular fracture, happened due to precipitate free zones around GBs in this material, we have to carry out TEM investigation during TEM Lab in week 14.